

#### **SEALING**

Make

# VIBRATION CONTROL

CABIN AIR FILTER

Corteco Service Information No. 00012-EN

Service Information: Design update and new material enhancement

Corteco No 220116S / 220054H

OE-Reference 0311.29, 1146063

PSA, Ford

Model / Engine C3, C4, DS3, 208, 308, 407, Fiesta, Focus, Mondeo...

Please see TecDoc catalogue for detailed information



# Design update of 220116S and 220054H

The design and material of oil drain plug 220116S and 220054H has been updated.

Due to excessive torque generally applied during installation – higher than the manufacturer's recommendation – a risk of breakage existed with the old design. To encounter this situation, Corteco optimized these plugs by adapting the design and using a material with homogenous grain structure. This provides the oil drain plug with enough strength to withstand the highest torque.



Figure 1: Updated design and material for 220116S and 220054H

#### **Technical reminder**

To obtain the best sealing and avoid the risk of breakage, car manufacturers recommend for these plugs a maximum torque of : 25 N.m.





Don't take a risk – Choose Corteco original quality.



Figure 2: Old design and material for 220116S and 220054H

### Corteco - Original quality equipment from Freudenberg











